

NADA/Fixed Operation 1

**2) Perpetual Inventory Bin Count**

Alex Padilla and myself, printed the Bin Report from Tekion DMS. We will count **BIN NUMBER 116**, with associated part numbers.

The overall condition of the shelves and cleanliness was good. A few wayward crews that are for license plates was sitting on the shelf. Probably, someone was in a hurry and tossed the crews on this shelf.

We found PART # 1354046030 was "over" by 1. After discussing with Alex, the consensus was that a technician brought the part back and the parts advisor did not account for the return.

PART # 1356410010 was "short" by 3. These are Timing Belt/Chain replacement labels. The consensus was that the parts advisor gave out too many on the last RO – the labels were probably sticking together.

BIN NUMBER	PART NUMBER	PART DESCRIPTION	ON HAND QTY	SHELF QTY	ON HOLD QTY	MULTIPLE BINS
116	1237150060	INSULATOR, ENGINE MO	0	0	0.00	NO
116	1237150200	INSULATOR, ENGINE MO	0	0	0.00	NO
116	130500P081	GEAR ASSY, CAMSHAFT	1	1	0.00	NO
116	1305046010	PULLEY ASSY, CAMSHAF	2	2	0.00	NO
116	135030A010	IDLER SUB-ASSY, TIMI	1	1	0.00	NO
116	135030F010	IDLER SUB-ASSY, TIMI	1	1	0.00	NO
116	135050A010	IDLER SUB-ASSY, TIMI	2	2	0.00	NO
116	135050F010	IDLER SUB-ASSY, TIMI	1	1	0.00	NO
116	1350520010	IDLER SUB-ASSY, TIMI	0		0.00	NO
116	1350520030	IDLER SUB-ASSY, TIMI	0		0.00	NO
116	1350546041	IDLER SUB-ASSY, TIMI	0	1	0.00	NO
116	135060T020	CHAIN SUB-ASSY	2	2	0.00	NO
116	1352146040	PULLEY, CRANKSHAFT T	1	1	0.00	NO
116	1354020021	TENSIONER ASSY, TIMI	0	0	0.00	NO
116	1354020030	TENSIONER ASSY, TIMI	1	1	0.00	NO
116	1354020040	TENSIONER ASSY, TIMI	1	1	0.00	NO
116	1354046030	TENSIONER ASSY, TIMI	1	2	0.00	NO
116	1354050030	TENSIONER ASSY, TIMI	1	1	0.00	NO
116	1356410010	LABEL, T/BELT REPLAC	11	2	0.00	NO
116	1356809070	BELT, TIMING	7	7	0.00	NO
116	1356809080	BELT, TIMING	8	0	0.00	NO
116	1356859045	BELT, TIMING	0	0	0.00	NO

→ ?

← ?