

C/W R.O.	PART DESCRIPTION	ADVISOR NAME	PAID IN FULL	DATE ORDERED
525011	specer bushing	Adi	yes	10/2/2023
528796	thermostat	andy	no	12/8/2023
528796	o ring	andy	no	12/8/2023
535193	rim	andy	no	4/30/2024
536763	guide support	andy	no	5/23/2024
536763	left front sring	andy	no	5/23/2024
537090	steering gear	andy	yes	6/6/2024
537669	vibration generator	andy	no	6/10/2024
537854	wiper blades	robin	yes	6/12/2024
537528	set of clutch parts	Evan	no	6/17/2024
537528	flange	Evan	no	6/17/2024
330122	front break pad sen	orlando	no	6/27/2024
536564	grill front	adi	no	7/5/2024
538818	guide support	adi	no	7/8/2024
538845	side window door right	Robin	no	7/9/2024
534387	brake disc ventilated			7/16/2024
539080	spring ring shell	Robin	no	7/18/2024
539080	set of seals	rob	no	7/18/2024
330860	lower air flaps	levant	yes	7/24/2025
App-	trim panel	Robin	no	07/09.2024

Print this out and bring to parts class. Write

**PLEASE POST THE OLDEST
SOP'S FIRST**

Please pl

DATE ARRIVED	DATE CUST NOTIFIED	APPT DATE	TOTAL DAYS ON SHELF	COST \$	RETURN TO OE DATE
10/4/2023	10/4/2023	na	297	4.04	
12/08.2023	12/08.2023	na	227	108.43	
12/08.2023	12/08.2023	na	227	8.19	
5/16/2024	5/17/2024	TBD	70	909.18	
5/24/2024	7/25/2024	na	69	144.69	
7/19/2024	7/25/2024	TBD	6	309.32	
6/7/2024	6/7/2024	na	49	4254.37	
6/11/2024	7/25/2024	TBD	44	149.04	
6/13/2024	6/13/2024	na	45	52.5	
6/25/2024	6/25/2024	TBD	30	784.33	
6/19/2024	6/25/2024	na	44	16.64	
6/28/2024	7/28/2024	na	34	23.68	
7/6/2024	7/6/2024	in shop	20	300.92	
7/9/2024	7/9/2024	na	16	159x2	
7/24/2024	7/24/2024	7/29/2024	1	808.44	
7/16/2024	7/16/2024	TBD	8	435.9	
7/18/2024	7/18/2024	na	7	3.71	
7/18/2024	7/18/2024	na	7	49.67	
7/25/2024	7/25/2024	NA	1	343.75	
7/25/2024	7/25/2024	TBD	1	153.32	

8860.12

your name, class # and brand on the top right.	Please add up the cost of all parts that are enter
--	--

Place this into your class site drop box called 20 SOP
 Exercise when completed

PUT IN STOCK DATE	Omar Yusofi, class N453, BMW
	paid in full, no show will scrap
	customer dissapeared
	customer dissapeared
	winter tire on rim, damaged
	back ordered part- part of bigger repair waited for B/O
	back ordered part- part of bigger repair waited for B/O
	insurnace paid
	ro still open,/ not safety retalted item will have client come back
	customer did not show up to install
	car on site, client not in a rush
	car on site, client not in a rush
	will drop by when he can
	in the shop
	waiting for more parts to arrive, client is aware
	waiting for more parts to arrive, client is aware
	waiting for more parts to arrive, client is aware
	car was on site awaiting part
	car was on site awaiting part
	paid in full
	back ordered part- released

red into column "J"

525011	specer bushing	Adi	yes	10/2/2023	10/4/2024	10/4/2024
528796	thermostat	andy	no	12/8/2023	12/08.2023	12/08.2023
528796	o ring	andy	no	12/8/2023	12/08.2023	12/08.2023
535193	rim	andy	no	4/30/2024	5/16/2024	5/17/2024
536763	guide support	andy	no	5/23/2024	5/24/2024	7/25/2024
536763	left front sring	andy	no	5/23/2024	7/19/2024	7/25/2024
537090	steering gear	andy	yes	6/6/2024	6/7/2024	6/7/2024
537669	vibration generator	andy	no	6/10/2024	6/11/2024	7/25/2024
537854	wiper blades	robin	yes	6/12/2024	6/13/2024	6/13/2024
537528	set of clutch parts	Evan	no	6/17/2024	6/25/2024	6/25/2024
537528	flange	Evan	no	6/17/2024	6/19/2024	6/25/2024
330122	front break pad ser	orlando	no	6/27/2024	6/28/2024	7/28/2024
536564	grill front	adi	no	7/5/2024	7/6/2024	7/6/2024
538818	guide support	adi	no	7/8/2024	7/9/2024	7/9/2024
538845	de window door rig	Robin	no	7/9/2024	7/24/2024	7/24/2024
534387	brake disc ventilated			7/16/2024	7/16/2024	7/16/2024
539080	spring ring shell	Robin	no	7/18/2024	7/18/2024	7/18/2024
539080	set of seals	rob	no	7/18/2024	7/18/2024	7/18/2024
330860	lower air flaps	levant	yes	7/24/2025	7/25/2024	7/25/2024
App-	trim panel	Robin	no	07/09.2024	7/25/2024	7/25/2024

na	297	4	paid in full, no show will scrap
na	227	108.43	customer dissapeared
na	227	8.19	customer dissapeared
TBD	70	909.18	winter tire on rim, damaged
na	69	144.69	back ordered part- part of bigger repair waited for B/O
TBD	6	309.32	back ordered part- part of bigger repair waited for B/O
na	49	4254.37	insurnace paid
TBD	44	149.04	ro still open,/ not safety retalted item will have client come back
na	45	52.5	customer did not show up to install
TBD	30	784.33	car on site, client not in a rush
na	44	16.64	car on site, client not in a rush
na	34	23.68	will drop by when he can
in shop	20	300.92	in the shop
na	16	159x2	waiting for more parts to arrive, client is aware
7/29/2024	1	808.44	waiting for more parts to arrive, client is aware
TBD	8	435.9	waiting for more parts to arrive, client is aware
na	7	3.71	car was on site awaiting part
na	7	49.67	car was on site awaiting part
NA	1	343.75	paid in full
TBD	1	153.32	back ordered part- released

