

CUSTOMER #: 244199

879777

LARSON AUTOMOTIVE GROUP

ACCOUNTING

LARSON PORSCHE AUDI

Evan Trindle
PO Box 1855
Port Orchard, WA 98366
HOME:360-551-3548 CONT:360-551-3548
BUS: CELL:360-551-3548

PAGE 1

1701 Alexander Ave.
Fife, WA 98424
Phone: (253) 475-3832

SERVICE ADVISOR: 4784 ANDREW R LEWIS

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN/OUT, TAG. Row 1: 08, AUDI A3 2.0T, WAUNF78P88A028792, 103950/103952, T365.

Table with columns: DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Row 1: 01JAN08 DD, 10:48 27FEB23, 0.00, VISA, 04MAR23.

Table with columns: R.O. OPENED, READY, OPTIONS.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Row 1: A STARTING SYSTEM. CUSTOMER STATES THE CAR HAS TO BE JUMPED TO START.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Row 1: 05AUZ STARTING SYSTEM. CUSTOMER STATES THE CAR HAS TO BE JUMPED TO START.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Row 1: B FUEL SYSTEM. CUSTOMER STATES THE CHECK ENGINE LIGHT IS ON.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Row 1: 03AUZ FUEL SYSTEM. CUSTOMER STATES THE CHECK ENGINE LIGHT IS ON.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Row 1: C PLEASE PERFORM VIDEO AND VISUAL MULTI-POINT VEHICLE INSPECTION FOR CUSTOMER AS COURTESY.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Row 1: D\*\* RR TAILHGT BULB REPLACEMENT (Service added 02-24-2023 at 14:30:31 by ANDREW LEWIS).

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Row 1: BE88 RR TAILHGT BULB REPLACEMENT.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Row 1: E\*\* Bulb, Side Lamp Marker/Flasher - Replace (Service added 02-24-2023 at 14:30:31 by ANDREW LEWIS).

Table with columns: DESCRIPTION, TOTALS. Includes sections for Thank you, DISCLAIMER OF WARRANTIES, TERMS, and PLEASE PAY THIS AMOUNT.

Signature

CUSTOMER #: 244199

879777

LARSON AUTOMOTIVE GROUP

ACCOUNTING

LARSON PORSCHE AUDI

Evan Trindle
PO Box 1855
Port Orchard, WA 98366
HOME:360-551-3548 CONT:360-551-3548
BUS: CELL:360-551-3548

PAGE 2

1701 Alexander Ave.
Fife, WA 98424
Phone: (253) 475-3832

SERVICE ADVISOR: 4784 ANDREW R LEWIS

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Row 1: 08, AUDI A3 2.0T, WAUNF78P88A028792, 103950/103952, T365.

Table with columns: DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Row 1: 01JAN08 DD, 10:48 27FEB23, 0.00, VISA, 04MAR23.

Table with columns: R.O. OPENED, READY, OPTIONS. Row 1: 14:33 07FEB23, 13:24 01MAR23.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Includes service details for battery replacement.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Includes service details for vacuum pump and oil clean.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Includes service details for thermostat housing.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Includes service details for coolant.

Table with columns: DESCRIPTION, TOTALS. Includes financial summary and terms of service.

Signature

CUSTOMER #: 244199

879777

LARSON AUTOMOTIVE GROUP

ACCOUNTING

LARSON PORSCHE AUDI

1701 Alexander Ave.
Fife, WA 98424
Phone: (253) 475-3832

Evan Trindle
PO Box 1855
Port Orchard, WA 98366
HOME:360-551-3548 CONT:360-551-3548
BUS: CELL:360-551-3548

PAGE 3

SERVICE ADVISOR: 4784 ANDREW R LEWIS

Table with columns: COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG. Values: 08, AUDI A3 2.0T, WAUNF78P88A028792, 103950/103952, T365.

Table with columns: DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE. Values: 01JAN08 DD, 10:48 27FEB23, 0.00, VISA, 04MAR23.

Table with columns: LINE, OPCODE, TECH, TYPE, A/HRS, S/HRS, LIST, NET, TOTAL. Description: REPLACEMENT OF THERMOSTAT HOUSING. REMOVED AIR BOX ASSEMBLY, REMOVED DRIVE BELT, LOCKED SERPENTINE BELT TENSIONER, REMOVED ALTERNATOR, REMOVED FRONT CHARGE AIR PIPE, LOOSENED FRONT COOLANT PIPE, REMOVED COOLANT HOSES AND PIPES TO THERMOSTAT, REMOVED THERMOSTAT, CLEANED MATING SURFACES, INSTALLED NEW THERMOSTAT, INSTALLED ALL REMOVED PARTS IN REVERSE ORDER. CLEANED VEHICLE OF COOLANT AND VACUUM FILLED COOLING SYSTEM. VERIFIED NO LEAKS AND ENGINE NOW PROPERLY COMES TO OPERATING TEMPERATURE

\*\*\*\*\*
ESTIMATE: 2,893.53 24FEB23 14:30 SA: 4784
CONTACT:
\*\*\*\*\*

CUSTOMER PAY SHOP SUPPLIES / HAZA 500 500 5.00
\*\*\* NO RO PUNCH TIMES ON FILE \*\*\*

Table with columns: TRGT/ACCOUNT, SALE, COST, CONTROL. Values: 8/5500 149485 22880 8/5560 0 0, 8/5700 86300 42478 8/5750 22560 13160, 8/0543 500 500 8/3240 25885 0, 8/0163 0 \*\*\*\*\* 8/2250 284730 \*\*\*\*\*

COST, SALE, & COMP TOTALS 79018 258845 0

Table with columns: DESCRIPTION, TOTALS. Rows include: LABOR AMOUNT 1494.85, PARTS AMOUNT 1088.60, GAS, OIL, LUBE 0.00, SUBLET AMOUNT 0.00, MISC. CHARGES 5.00, TOTAL CHARGES 2588.45, LESS INSURANCE 0.00, SALES TAX 258.85, PLEASE PAY THIS AMOUNT 2847.30.

Signature